

## Firmware 15.42 Release Notes

Horner Automation has released a new Firmware revision for the **XL+.** This is available for download from the firmware section at the following websites:

North American Website <a href="https://hornerautomation.com/controller-firmware">https://hornerautomation.com/controller-firmware</a></a>
<a href="https://www.hornerautomation.eu/support/firmware/">https://www.hornerautomation.eu/support/firmware/</a>

**NOTE**: This Firmware release requires bootloader to be installed. It is not an option.

Latest System File Revisions		
Firmware	15.42	
OS Version	4.9.12.3	
FPGA	0.1	

## A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

NEW FEATURE
Support has been provided to add user customized keyslide image.

FIRMWARE 15.42 CORRECTED ISSUES		
1	Resolved screen capture issue where the captured images display incorrect colors when viewed on a PC screen.	
2	Resolved an issue where an FTP Failure error message is displayed while publishing webpages (WebMI).	
3	Resolved an issue where the XL+ suffers a system exception under the following conditions: 1. 2nd user is logged in to WebMI webpages 2. 2nd user attempts to access a webpage that has an embedded Alarm History object. 3. Controller is currently displaying the same page	

## **Technical Support**

North America:	Europe:
Tel: (317) 916-4274	Tel: (+353)-21-4321-266
Fax: (317) 639-4279	Fax: (+353)-21-4321826
Website: <a href="https://hornerautomation.com">https://hornerautomation.com</a>	Website: <a href="https://www.hornerautomation.eu/">https://www.hornerautomation.eu/</a>
Email: <u>techsppt@heapg.com</u>	Email: technical.support@horner-apg.com