



## 14.26 Firmware Release for XL4, XL7, EXL6, EXL10 and X5

Horner APG has released Firmware Revision 14.24 for the XL4, XL7, EXL6, EXL10, and X5 OCS.

Firmware Revision 14.26 is available for download from the firmware section of the US website, <http://www.heapg.com/content/11-controller-firmware>, or the European website, <http://www.horner-apg.com/en/download/ocs.aspx>.

### A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

## Firmware 14.26 - Issues Resolved

Issues Resolved	
1.	Noise during power up caused the unit to run from the battery and not switch to mains power resulting in battery drain. To recover the unit, battery had to be taken out.
2.	Bezel color bug fix for Grey color in Linux controllers.

## Firmware 14.26 - Known Issues Under Review

Known Issues	
1.	Ethernet Upload / Download delays when exchanging big packets
2.	OCS resets when a USB camera is plugged directly into a powered-up unit; only happens with some USB cameras
3.	On startup, the battery status is reported as faulty although it is not. This gets corrected by the time the units starts
4.	If Retentive trends with log is enabled with Multi language option, then two log files are created in Micro sd. Instead of logging data in single file ,it is logging in two different files as we switch between languages

## Technical Support

### North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Web: <http://www.heapg.com>

Email: [techspt@heapg.com](mailto:techspt@heapg.com)

### Europe:

Tel: +353 (0)21 4321 266 Ext 202

Fax: +353 (0)21 4321 826

Web: <http://www.horner-apg.com>

Email: [technical.support@horner-apg.com](mailto:technical.support@horner-apg.com)