

14.18 Firmware Release for RCC Product

Horner APG has released Firmware Revision 14.18 for the RCC controller.

This is available for download from the firmware section of the US website, <http://www.heapg.com/content/11-controller-firmware>, or the European website, <http://www.horner-apg.com/en/download/ocs.aspx>.

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Firmware 14.18 Enhancements

Feature Enhancements	
1.	Modbus fill (40513 -42999)
2.	Added support for Modbus TCP server disconnection and reconnection
3.	Added HE-RCC8842

Firmware 14.18 - Issues Resolved

Issues Resolved	
1.	System exception with serial protocol manual selection on subsequent power cycle
2.	IP and port through registers for XL4 and RCC in Modbus Client protocol
3.	User Security Configuration using registers
4.	Serial port slow - fixes
5.	Swap Dword issue with protocols
6.	Protocol fix for update interval >0
7.	Protocol fix for Manual trigger

Firmware 14.18 - Known Issues Under Review

Known Issues	
1.	Ethernet Upload / Download delays when exchanging big packets

Technical Support

North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Web: <http://www.heapg.com>

Email: techspt@heapg.com

Europe:

Tel: +353 (0)21 4321 266 Ext 202

Fax: +353 (0)21 4321 826

Web: <http://www.horner-apg.com>

Email: technical.support@horner-apg.com