



## 14.26 Firmware Release for RCC Product

Horner APG has released Firmware Revision 14.26 for the RCC controller.

This is available for download from the firmware section of the US website, <http://www.heapg.com/content/11-controller-firmware>, or the European website, <http://www.horner-apg.com/en/download/ocs.aspx>.

### A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

### Firmware 14.26 - Issues Resolved

| Issues Resolved |   |
|-----------------|---|
| 1.              | Noise during power up caused the unit to run from the battery and not switch to mains power resulting in battery drain. To recover the unit, battery had to be taken out. |
| 2.              | Check for date removed for webMi License for RCC972 Cscan, ACNopen and J1939 variants.  |

### Firmware 14.26 - Known Issues Under Review

| Known Issues |   |
|--------------|---|
| 1.           | Ethernet Upload / Download delays when exchanging big packets |

#### Technical Support

##### North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Web: <http://www.heapg.com>

Email: [techspt@heapg.com](mailto:techspt@heapg.com)

##### Europe:

Tel: +353 (0)21 4321 266 Ext 202

Fax: +353 (0)21 4321 826

Web: <http://www.horner-apg.com>

Email: [technical.support@horner-apg.com](mailto:technical.support@horner-apg.com)