

14.10 Firmware Release for RCC Product

Summary

Horner APG announces the availability of Firmware Revision 14.10 for the RCC controller. This is available for download from the firmware section of the US web site, <https://www.heapg.com/support/controller-firmware/> or the European web site, <http://www.horner-apg.com/en/download/ocs.aspx>

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of new firmware.

Factory Revision Letters for Deployment of Firmware Revision 14.10

Product	Firmware Revision Letter (Note the second letter indicates Firmware Revision)
HE-RCC972	G

Firmware 14.10 Enhancements – Feature Enhancements

Feature Enhancements	
1.	Modbus UDP Master/Slave Support being added with Cscape 9.6 SP3
2.	Suppression of responses to Modbus broadcast commands in slave blocks

Firmware 14.10 – Issues Resolved

Issues Resolved	
1.	Corrected latency in communications occurring when Modbus TCP and serial protocols used at the same time
2.	Corrected cfg partition issue with NAND
3.	Corrected issue with cold junction temperature calculation for temperatures below 0°C

North America:

Tel: (317) 916-4274
 Fax: (317) 639-4279
 Web: <http://www.heapg.com>
 Email: techspt@heapg.com

Europe:

Tel: +353 (0)21 4321 266 Ext 202
 Fax: +353 (0)21 4321 826
 Web: <http://www.horner-apg.com>
 Email: technical.support@horner-apg.com