



# 14.02 Firmware Release for the RX371, QX351, and QX501

# Summary

Horner APG announces the availability of Firmware Revision 14.02 for the OCS Controller RX371, QX351, and QX501 models. This is available for download from the firmware section of the US web site, <a href="https://www.heapg.com/support/controller-firmware/">https://www.heapg.com/support/controller-firmware/</a> or the European web site, <a href="https://www.horner-apg.com/en/download/ocs.aspx">https://www.horner-apg.com/en/download/ocs.aspx</a>

#### A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of new firmware.

#### Factory Revision Letters for Last Released Version of Products (Pre 14.02)

Product	Revision Letter (Note the second letter
	indicates Firmware Revision)
HE-RX371	DJ
HE-QX351	CL
HE-QX501	EE
HEQX501C1XX	EE
HEQX351C1XX	BL

### Firmware 14.02 Enhancements - Feature Enhancements

	Feature Enhancements
1.	Historical Trend Support including Logging and Playback
2.	Grid Line Support for Trends and Graphs
3.	Object and Background Gradient Support
4.	Bitmap Transparencies
5.	Up and Down Key Support for the Recipe Object
6.	CsCAN Networking Block Support in IEC61131 with Array of Structure
7.	Passive FTP Mode
8.	Full Support of Smart Block Family
9.	Extended Bit Register (> %R2048) Support for Contacts and Coils
10	Increased CsCAN Ethernet Packet Size





#### Firmware 14.02 - Issues Resolved

Issues Resolved		
1.	Corrected Previously Known Issue of with Auto Load feature with compact flash cards of greater than 2G.	
2.	32 Bit Counter Passing Power Before Reaching the Set-point when the Reset is Enabled	
3.	Removable Media Object – Color Updates Correctly for Card Full Status	
4.	Reconnection issue with Modbus TCP/IP Server Protocol	
5.	RM Object Not Opening to the Root Directory when Unicode is Selected	
6.	Schedule Objects in Ladder not Passing Power when Set to Registers	

If assistance or additional information is required, contact:

# North America: Europe:

Tel: (317) 916-4274 Tel: +353 (0)21 4321 266 Ext 202

Fax: (317) 639-4279 Fax: +353 (0)21 4321 826 Web: http://www.heapg.com Web: http://www.horner-apg.com