



14.26 Firmware Release for ZX Products

Horner APG has released Firmware Revision 14.26 for the ZX line of OCS controllers.

This is available for download from the firmware section of the US website, <http://www.heapg.com/content/11-controller-firmware>, or the European website, <http://www.horner-apg.com/en/download/ocs.aspx>.

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Firmware 14.26 - Issues Resolved

Issues Resolved	
1.	Resolved crash when webmi is accessed from devices having higher latency
2.	UTC issue when Day light saving flag is high and units is power cycled

Firmware 14.26 - Known Issues Under Review

Known Issues	
1.	If Retentive trends with log is enabled with Multi language option, then two log files are created in Micro sd. Instead of logging data in single file ,it is logging in two different files as we switch between languages
2.	If the unit is power cycled in a month that has less than 31 days between the local and UTC time, the UTC date is incremented to 31

Technical Support

North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Web: <http://www.heapg.com>

Email: techspt@heapg.com

Europe:

Tel: +353 (0)21 4321 266 Ext 202

Fax: +353 (0)21 4321 826

Web: <http://www.horner-apg.com>

Email: technical.support@horner-apg.com