

Firmware 15.40 Release Notes

Horner Automation has released a new Firmware revision for the X2, XLE, XLT, XLEe, XLTe

This is available for download from the firmware section at the following websites:

North American Website: <https://hornerautomation.com/controller-firmware>

European Website: <http://www.hornerautomation.eu/support/firmware>

Latest System File Revisions	X2	XLE, XLT, XLEe, XLTe
Firmware	15.40	15.40
BIOS	0.15	0.28
CPLD	1.0	2.0

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Firmware 15.40 Enhancements:

Firmware 15.40 ENHANCEMENTS		Requires Cscape 9.90 SP3
1.	Downloadable protocol enable/disable options now available for full Network and also for individual devices	X
2.	Email with TLS encryption support (Ethernet based units only)	X
3.	Structure support in RM blocks	X
4.	Load of firmware using MicroSD (Ethernet based units only)	

Corrected Issues for Firmware 15.40

Firmware 15.40 Corrected Issues		Requires Cscape 9.90 SP3
1.	Setpoints not loaded when loading .pgm file in controller with Cscape 9.90 SP1 & SP2	X
2.	CsCAN ladder blocks can now use registers greater than %R2048	X
3.	PID blocks, Modbus master and slave blocks, Alarm block can now use registers greater than %R2048	X
4.	Fixed an issue with uploading XLT program	
5.	Reduced Jitter for analog inputs, making them more stable	
6.	Fixed an issue where some SmartBlock modules were not communicating properly with XLE	

Technical Support:

North America: Tel: (317) 916-4274 Fax: (317) 639-4279 Website: https://hornerautomation.com Email: techsppt@heapg.com	Europe: Tel: (+353)-21-4321-266 Fax: (+353)-21-4321826 Website: http://www.hornerautomation.eu Email: technical.support@horner-apg.com
---	---