

15.28 Firmware Release for X4

Horner Automation has released new Firmware for the X4.

This is available for download from the firmware section at the following websites:

North American Website <https://hornerautomation.com/controller-firmware/>
European Website <http://www.hornerautomation.eu/support/firmware/>

Latest System Firmware, Boot and CPLD for X4
Firmware 15.28
Boot 0.28
CPLD 0.9

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Firmware 15.28 – Corrected Issues

ISSUES
Pressing objects on the touchscreen in continuous, rapid succession with the beeper enabled (System Menu → Set Beeper) could cause an undesired switching of digital inputs. This issue does not occur if the internal beeper is turned off.

Issues apply to the following revisions:	
Global Product Part Numbers	Revision Number
HE-X4A	Rev CC or later
HE-X4R	Rev BC or later

NOTE: Controller Revision Level – Horner controllers have a two-letter revision level. The **first letter** of the revision is the HARDWARE REVISION, and the **second letter** of the revision is the FIRMWARE REVISION.

Technical Support

<p>North America: Tel: (317) 916-4274 Fax: (317) 639-4279 Website: https://hornerautomation.com Email: techsppt@heapg.com</p>	<p>Europe: Tel: (+) 353-21-4321-266 Fax: (+353)-21-4321826 Website: www.hornerautomation.eu Email: technical.support@horner-apg.com</p>
--	--