

15.24 Firmware Release for XLE, XLEe, XLT, XLTe

Horner Automation has released new Firmware for the XLE, XLEe, XLT, XLTe.

This is available for download from the firmware section at the following websites:

North American Website <https://hornerautomation.com/controller-firmware>
European Website <http://www.hornerautomation.eu>

NOTE: When performing a Firmware update, always select Install Bootloader so that all system files are updated.

XLE, XLEe, XLT, XLTe
Firmware 15.24
BIOS 0.28
CPLD 2.0

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Firmware 15.24 – Corrected Issues

ISSUE
<p>Could not load 15.20 Firmware and new CPLD on new blank XLE units.</p> <p>NOTE: Does not affect post-production units that are flashed with earlier versions.</p>

Controller Revision Level: Horner controllers have a two-letter revision level. The **first letter** of the revision is the HARDWARE REVISION, and **the second letter** of the revision is the FIRMWARE REVISION.

Technical Support

<p>North America: Tel: (317) 916-4274 Fax: (317) 639-4279 Website: https://hornerautomation.com Email: techsppt@heapg.com</p>	<p>Europe: Tel: (+) 353-21-4321-266 Fax: (+353)-21-4321826 Website: http://www.hornerautomation.eu Email: technical.support@horner-apg.com</p>
---	--