

## Firmware 15.34 Release Notes

---

Horner Automation has released a new Firmware revision for the **XL4, XL7, EXL6, EXL10, RCC8842, RCC2414, RCC972, RCC1410**.

This is available for download from the firmware section at the following websites:

North American Website     <https://hornerautomation.com/controller-firmware>  
European Website             <http://www.hornerautomation.eu>

**NOTE:** This Firmware release requires bootloader to be installed. It is not an option.

Latest System File Revisions	
Firmware	15.34
OS Version	2.6.35.74
InitRd	1.18

### A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

CORRECTED ISSUES	
1.	Fixed an issue on internal I/O bus timing preventing the unit from shutting down properly and saving registers.
2.	Fixed an issue where a fast power cycle (less than 2 seconds) caused the unit to run on internal battery causing an improper shut down.
3.	Fixed a watchdog issue related to the Horner Wi-Fi module performing a mode change.
4.	Fixed an issue where some applications using the email feature with TLS enabled causing a watchdog reset.

### Technical Support

<b>North America:</b> Tel: (317) 916-4274 Fax: (317) 639-4279 Website: <a href="https://hornerautomation.com">https://hornerautomation.com</a> Email: <a href="mailto:techsppt@heapg.com">techsppt@heapg.com</a>	<b>Europe:</b> Tel: (+353)-21-4321-266 Fax: (+353)-21-4321826 Website: <a href="http://www.hornerautomation.eu">http://www.hornerautomation.eu</a> Email: <a href="mailto:technical.support@horner-apg.com">technical.support@horner-apg.com</a>
--	--