

15.02 Firmware Release for RCC972, RCC1410, RCC2414, and RCC8842

Horner Automation has released Firmware revision for the RCC972, RCC1410, RCC2414, and RCC8842.

This is available for download from the firmware section at the following websites:

North American Website: <https://hornerautomation.com/controller-firmware/>

European Website: <http://www.horner-apg.com/en/download.aspx>

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Firmware 15.02 – Issues and Fixes

	ISSUES	FIXES
1.	Email was not being sent if username and password were not configured.	Corrected.
2.	In certain applications, applications with continuous read, write, copy, and delete operations to the microSD, it could result in watchdog reset or an incorrect error status blocking further operations to micro SD.	Corrected.
3.	In WebMI applications if sample rate for trends was configured to use registers instead of constants, it was not working.	Corrected.

Technical Support

North America: Tel: (317) 916-4274 Fax: (317) 639-4279 Website: https://hornerautomation.com Email: techsppt@heapg.com	Europe: Tel: (+) 353-21-4321-266 Fax: (+353)-21-4321826 Website: www.horner-apg.com Email: tech.support@horner-apg.com
--	--