

15.04 Firmware Release for XL4e, XL7e, EXL6e and EXL10e

Horner Automation has released Firmware revision 15.04.

This is available for download from the firmware section of the Horner Automation website.

North America	https://hornerautomation.com/controller-firmware/
Europe	http://www.horner-apg.com/en/download/ocs.aspx

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Bug Fixes in Firmware 15.04 (Kernel 2.6.35.55 and FPGA ver 0.6)

Bug Fixes	
1.	All HSC counters when selected for "frequency" behaves correctly now instead of working as totalizer.
2.	Modbus slave device did not respond to commands if Datalengths were of a certain value in RS232 and full duplex RS485.
3.	Touch screen now works correctly after performing Load Clone which was saved with firmware prior to 15.02.
4.	Slow communications seen with XRC9 in previous firmware are fixed.

Technical Support

United States:

Tel: (317) 916-4274

Fax: (317) 639-4279

Website: <https://hornerautomation.com>

Email: techsppt@heapg.com

Europe:

Tel: (+) 353-21-4321-266

Fax: (+353)-21-4321826

Website: www.horner-apg.com

Email: technical.support@hornerapg.com