

15.22 Firmware Release for XLT and XLTe

Horner Automation has released a new Firmware revision for the XLT and XLTe.

This is available for download from the firmware section at the following websites:

North American Website <https://hornerautomation.com/controller-firmware/>
European Website <http://www.horner-apg.com/en/download.aspx>

NOTE: When performing a firmware update, always perform auto update or full update from Cscape so that all files are updated.

Latest System File Revisions	
Firmware	15.22
Boot	.027
CPLD	2.0

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Firmware 15.22 Fix:

Corrected Issue for XLT and XLTe
Added commands to the display update block for recovering from split screen.

Technical Support

North America: Tel: (317) 916-4274 Fax: (317) 639-4279 Website: https://hornerautomation.com Email: techsppt@heapg.com	Europe: Tel: (+) 353-21-4321-266 Fax: (+353)-21-4321826 Website: www.horner-apg.com Email: technical.support@horner-apg.com
--	--