HORNER
AUTOMATION GROUP

OCS

14.06 Firmware Release for RCC Product

Summary

Horner APG announces the availability of Firmware Revision 14.06 for the RCC controller, corresponding with Cscape 9.6. This is available for download from the firmware section of the US web site, https://www.heapg.com/support/controller-firmware/ or the European web site, http://www.horner-apg.com/en/download/ocs.aspx

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of new firmware.

Factory Revision Letters for Deployment of Firmware Revision 14.06

Product	Revision Letter (Note the second letter indicates Firmware Revision)
HE-RCC972	E

Firmware 14.06 Enhancements – Feature Enhancements

Feature Enhancements	
1.	Email SSL Support
2.	BACnet protocol support

Firmware 14.06 – Issues Resolved

Issues Resolved	
1.	Scan rate jump when pop up is active in Linux
2.	J1939 issue with same PGN and different source address
3.	FTP bug fix for filezilla
4.	Modbus TCP scanlist >16 issue
5.	SFC step timing and parallel execution bug fix
6.	Timer Object minimum setting ignored
7.	Recipes - the 11th product name cannot be edited correctly
8.	EGD Multicast doesn't recover from cable unplug and re-plug

North America:

Tel: (317) 916-4274
Fax: (317) 639-4279
Web: http://www.heapg.com
Email: techsppt@heapg.com

Europe:

Tel: +353 (0)21 4321 266 Ext 202
Fax: +353 (0)21 4321 826
Web: http://www.horner-apg.com
Email: technical.support@horner-apg.com