

## 15.26 Firmware Release for X4

---

Horner Automation has released new Firmware for the X4.

This is available for download from the firmware section at the following websites:

**North American Website**      <https://hornerautomation.com/controller-firmware/>  
**European Website**              <http://www.horner-apg.com/en/download.aspx>

Latest System Firmware, Boot and CPLD for X4
Firmware 15.26
Boot 0.28
CPLD 0.9

**A NOTE ABOUT FIRMWARE UPDATES:**

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

### Firmware 15.26 – Corrected Issues

ISSUES
1. During boot up, the analog outputs are ON at a level of approximately 20mA for up to two (2) seconds.
2. Analog and touchscreen calibration data cannot be accessed by the firmware, reducing analog and touchscreen accuracy

Issues apply to the following revisions:	
Global Product Part Numbers	Revision Number
HE-X4A	Rev CC or earlier
HE-X4R	Rev BC or earlier

**NOTE: Controller Revision Level** – Horner controllers have a two-letter revision level. The **first letter** of the revision is the HARDWARE REVISION, and **the second letter** of the revision is the FIRMWARE REVISION.

### Technical Support

North America: Tel: (317) 916-4274 Fax: (317) 639-4279 Website: <a href="https://hornerautomation.com">https://hornerautomation.com</a> Email: <a href="mailto:techsppt@heapg.com">techsppt@heapg.com</a>	Europe: Tel: (+) 353-21-4321-266 Fax: (+353)-21-4321826 Website: <a href="http://www.horner-apg.com">www.horner-apg.com</a> Email: <a href="mailto:technical.support@horner-apg.com">technical.support@horner-apg.com</a>
---	---