

## 14.04 Firmware Release for XLe and XLt

### Summary

Horner APG announces the availability of Firmware Revision 14.04 for the OCS Controller Models XLe and XLt. This is available for download from the firmware section of the US web site, <https://www.heapg.com/support/controller-firmware/> or the European web site, <http://www.horner-apg.com/en/download/ocs.aspx>

### A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of new firmware.

### Factory Revision Letters for Deployment of Firmware Revision 14.04

Product	Firmware Revision Letter (Note the second letter of Rev)
HE-XE100, HE-XE102, HE-XE103, HE-XE104, HE-XE105	S
HEXE220C000,HEXE220C012,HEXE220C013,HEXE220C014 HEXE220C015,HEXE220C100,HEXE220C112,HEXE220C113 HEXE220C114,HEXE220C115	S
HE-XT100, HE-XT102, HE-XT103, HE-XT104, HE-XT105	N
HEXT240C100,HEXT240C112,HEXT240C113,HEXT240C114 HEXT240C115	L
HEXT240C112-57	L

### Firmware 14.04 Enhancements – Feature Enhancements

Feature Enhancements	
1.	Email with SSL support
2.	Router software support for Cscape connectivity

## Firmware 14.06 – Issues Resolved

Issues Resolved	
1.	J1939 issue with same PGN and different source address
2.	SFC step timing and parallel execution bug fix
3.	Timer Object minimum setting ignored
4.	Recipes - the 11th product name cannot be edited correctly

If assistance or additional information is required, contact:

### North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Web: <http://www.heapg.com>

Email: [techsppt@heapg.com](mailto:techsppt@heapg.com)

### Europe:

Tel: +353 (0)21 4321 266 Ext 202

Fax: +353 (0)21 4321 826

Web: <http://www.horner-apg.com>

Email: [technical.support@horner-apg.com](mailto:technical.support@horner-apg.com)