

## 14.06 Firmware Release for NX Products

### Summary

Horner APG announces the availability of Firmware Revision 14.06 for the OCS Controller NX models, corresponding with Cscape 9.6 launch. This is available for download from the firmware section of the US web site, <https://www.heapg.com/support/controller-firmware/> or the European web site, <http://www.horner-apg.com/en/download/ocs.aspx>

### A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of new firmware.

### Factory Revision Letters for Deployment of Firmware Revision 14.06

Product	Revision Letter (Note the second letter indicates Firmware Revision)
HE-NX220, HE-NX221, HE-NX222	Z
HE-NX250, HE-NX251, HE-NX252	Z
HENX220C1XX, HE221CXXX	Z
HENX250C1XX, HENX251C1XX	Z

### Firmware 14.06 Enhancements – Feature Enhancements

Feature Enhancements	
1.	Email with SSL support
2.	Router software support for Cscape connectivity
3.	Improved Range of Standard Switch Icons

## Firmware 14.06 – Issues Resolved

Issues Resolved	
1.	J1939 issue with same PGN and different source address
2.	SFC step timing and parallel execution bug fix
3.	Timer Object minimum setting ignored
4.	Recipes - the 11th product name cannot be edited correctly
5.	14.02 firmware in NX251 SRTP doesn't recover from cable unplug and re-plug

If assistance or additional information is required, contact:

### North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Web: <http://www.heapg.com>

Email: [techsppt@heapg.com](mailto:techsppt@heapg.com)

### Europe:

Tel: +353 (0)21 4321 266 Ext 202

Fax: +353 (0)21 4321 826

Web: <http://www.horner-apg.com>

Email: [technical.support@horner-apg.com](mailto:technical.support@horner-apg.com)