



14.06 Firmware Release for the RX371, QX351, and QX501

Summary

Horner APG announces the availability of Firmware Revision 14.06 for the OCS Controller RX371, QX351, and QX501 models, corresponding with the launch of Cscape 9.6. This is available for download from the firmware section of the US web site,

https://www.heapg.com/support/controller-firmware/ or the European web site, http://www.horner-apg.com/en/download/ocs.aspx

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of new firmware.

Factory Revision Letters for Deployment of Firmware Revision 14.06

Product	Firmware Revision Letter (Note Second Letter of Rev.)
HE-RX371	M
HE-QX351	M
HE-QX501	Н
HEQX501C1XX	Н
HEQX351C1XX	M

Firmware 14.06 Enhancements – Feature Enhancements

Feature Enhancements	
1.	Email with SSL Support (QX501 Only)
	Router software support for Cscape connectivity
3.	127 characters support in ASCII object
4.	Improved Range of Standard Switch Icons
5.	Improved meters and gauges
6.	Button improvements with 3D style button
7.	Transparency in Animated text fields





Firmware 14.06 - Issues Resolved

Issues Resolved	
1.	J1939 issue with same PGN and different source address
2.	FTP bug fix for filezilla
3.	Modbus TCP scanlist >16 issue
4.	SFC step timing and parallel execution bug fix
5.	Timer Object minimum setting ignored
6.	Recipes - the 11th product name cannot be edited correctly

If assistance or additional information is required, contact:

North America: Europe:

Tel: (317) 916-4274 Tel: +353 (0)21 4321 266 Ext 202

Fax: (317) 639-4279 Fax: +353 (0)21 4321 826 Web: http://www.heapg.com Web: http://www.horner-apg.com