
Firmware 17.32 (Canvas) Release Notes

Horner Automation has released a new Firmware revision for the following **Canvas** products: **Canvas 4, Canvas 5, Canvas 7, Canvas 7D and Canvas 10D.**

This is available for download from the firmware section at the following websites:

North American Website <https://hornerautomation.com/controller-firmware>

European Website <http://www.hornerautomation.eu>

Latest System File Revisions for Products:	
Firmware	17.32
FPGA	0.2
Operating System	4.19.49
System Version	111

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of the new firmware.

Bug Fixes		Affected Controllers: All Canvas models, unless otherwise stated
#	Main Subject	Description
1.	Boot-Up Issue at Cold Temperatures	Resolved: Device boot-up issue at cold temperatures.

Known Issues		Affected Controllers: All Canvas models unless otherwise stated
#	Subject	Description
1.	WebMI 2.0 – Switch/Button Delayed Responsiveness	If the switch is turned to ON, it does not instantly turn on WebMI 2.0. Instead, it first turns on the device, and then it turns on WebMI 2.0.
2.	WebMI 2.0 – Mobile Devices	Multiple XY Graph / Trend objects, when configured in single screen, do not work on mobile devices.
3.	Video Object	The video object does not work for certain video Codecs like H264 – MPEG – 4 AVC (part10) (avc1).
4.	WI-FI in Client Mode	The device requires a power cycle for WI-FI to work, when the user downloads the WI-FI client program, after downloading the access mode program.
5.	Historical Data on the Webpage	The historical data of the Trend objects is not supported on web pages.
6.	PGM Load	If a user creates a .PGM file using Firmware 17.20, and then loads in an older / earlier firmware (earlier than Firmware 17.20), then the device is displaying a keypad pop-up instead of a failure message.
Canvas 10D Only		
7.	Splash Screen	Canvas 10D does not display the splash screen for a second time during boot-up, as do all other Canvas products.

Technical Support

North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Website: <https://hornerautomation.com>

Email: APGUSATechSupport@heapg.com

Europe:

Tel: (+353)-21-4321-266

Fax: (+353)-21-4321826

Website: <http://www.hornerautomation.eu>

Email: technical.support@horner-apg.com